

chinery
in it be

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if a
painted on Ship and n

Was a damage report made by anyone else? If so, by whom?



Lloyd's Register of Shipping, 71, Fenchurch Street,

London, 25th August, 1927.
E.C.3.

H.

To the Surveyors at NAGASAKI.

Lo-10-11-27

Vessel's Name, S.S. "TOYO MARU No 2"

QUESTION.

ANSWER.

With reference to the Boiler Survey which became due at the end of February last, I shall be glad if you will ascertain and let me know what arrangements have been made for the requisite inspection to take place.

C. J. J.

J. D. W.

Date:— 30th September 1927.

I regret to state that the Owner does not desire to continue with Lloyd's classification for this vessel but to continue with Japanese Kaiji Kyokai and in consequence vessel will not be submitted to this Society for survey.

The Hull & Machinery Classification Certificates and One Freeboard Certificate have been returned by the Owner and are forwarded herewith.

The Freeboard Certificate was originally issued in duplicate but it is not possible at present to trace the second certificate. This will be forwarded when returned by the Owner.

G. Anderson

Surveyor to Lloyd's Register

SEP 24 1927



© 2020

Lloyd's Register
Foundation

W1096-0073

er Items:—

Copper, or
(State
When pu

Boats

Masts, Yard

Condition, h

(State if

Sails

Equipment

Anchors, No.

Cables (State

length

Rule len

Hawser & W

Standing and

vessel in the Regi
to remain as clas

Committee's Minute

FRI. 4 NOV 1927

Thursday 10