

of excess of Hatchway
Do. above Crown of
Engine Room ...
Gross Tonnage

COPY FOR LONDON OFFICE.

Lloyd's Register of Shipping

TELEGRAMS: LLOYDS, CLEVELAND.

TELEPHONE 3910 MAIN

LLOYD'S REGISTER OF SHIPPING,

1403 ROCKEFELLER BUILDING.

CLEVELAND, O., 29th Dec. 1917.

LLOYD'S REGISTER
NEW YORK

The Secretary,
New York.

REC'D DEC 31 1917

ANS'D


Dear Sir,

Herewith we acknowledge your letter of the 27th instant concerning Report No. 108 on Steamer "War Penguin" and in reply to same we beg to state that the thickness of the Upper deck plating in way of bridge is 12.3 inches, the same as that in the sister vessel and as shown on the approved plans.

Yours very truly,

For the Surveyors,

Ernest Edwards.



W1096-0237

© 2020

Lloyd's Register
Foundation

Bulb Ang
Angles of
Spacing

Deck. Material and thickness