

1

Sent to Chief Surveyors... 17. 4. 41.

Received from Chief Surveyors.....

VESSEL'S NAME M. S. "British Science" Report Lir No. 115078

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey... Gen. Re. When due... 4. 41 - S. S. No. 2 pt. held.


Indented shell plating etc. in way of Nos. 1 and 2 tanks (s.s) and in way of Nos. 2 and 3 summer tanks (p.s) requires to be dealt with at Owners' convenience.

The 1st S.S. No. 2 was commenced at Birkenhead in 10.39 and advanced at Falmouth in the following April, but the greater part of the Survey still remains to be dealt with.

A General Examination was made in October last and a notation of 'Examined 10.40', valid for 6 months, assigned. A further General Examination consequently becomes due at the end of the present month.

In reply to enquiry the Owners write the ship is abroad and her future movements uncertain. They will, however, see that the necessary examinations are held at the first possible opportunity.

It is submitted action be deferred.



© 2019

Lloyd's Register Foundation

17. 4. 41

N 11-0006