

0.12.32.

to Chief Surveyors

Received from Chief Surveyors

SSEL'S NAME **BRITISH SCIENCE** Report **LIV.** No. **115078**

**For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

(**1<sup>ST</sup>** No. **2** **SURVEY PARTLY HELD.**) **DAMAGE + GEN. EXAMINATION**

en due **1-39**

When proposed to be completed


**EXAMINED 10-40-**  
**FOR 6 MONTHS.**

tion of Survey held, &c. *the lesser part.*

*now assigned*

*To complete the S.S. — See Pub. Rpt No 9939*

*Indented shell plating etc (S.S) in way of Nos 1 & 2 tanks and  
indented shell plating etc (P.S) in way of Nos 2 & 3 summer tanks  
require to be dealt with at the Owners convenience.*



© 2019

Lloyd's Register  
Foundation

**S.S. PART HELD**

W11-0010