

to Chief Surveyors _____

Received from Chief Surveyors **16 JAN 1929**

SEL'S NAME **s.s. "79.B".**

Report **London** No. **93433a.**

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/23.)

ure of Survey _____ When due _____

Built 10-1926 for the Argentine Government.

**The Modified Survey of the Oil Engines became
due 10,28.**


In reply to enquiry the Buenos Aires Surveyors
state that the Argentine Government do not desire to retain the vessel's
class in the Register Book.

It is submitted this vessel's class be withdrawn
from the Register Book and three dots, indicating withdrawal at Owners
request, be inserted in lieu.

Withdraw class.

Insert ...

14.1.29.



© 2020

Lloyd's Register
Foundation