

*Compulsory*

(Rpt. 12.)

FREEBOARD VERIFICATION FORM FOR STEAMERS.

Port Belfast When received in London Office 6<sup>th</sup> Feby. 1904

Vessel's Name T.S.S. "Matafua"

Official No. \_\_\_\_\_ No. in Reg. Book \_\_\_\_\_

Port of Registry (For Foreign Vessels) \_\_\_\_\_

Iron or Steel Steel State whether Classed by Lloyd's Register (Contemplated) \_\_\_\_\_

Name of Owners Shaw, Savill & Albion Co. Ltd. Date of Verification 4.2.04

I have to report that the Freeboard from the centre of disc to the top of the statutory deck line, and the lines in connection therewith, as given below, assigned by the Committee to this vessel, have been correctly marked on the vessel's sides, in accordance with the printed instructions:—

From centre of disc to top of statutory deck line	6	ft.	10 1/2	ins.
From centre of disc to top of statutory deck line at awning or part-awning deck . . . . .	-	ft.	-	ins.
Fresh water line above centre of disc . . . . .			7	ins.
Indian Summer line above centre of disc . . . . .			6 1/2	ins.
Winter line below centre of disc . . . . .			6 1/2	ins.
<del>Winter North Atlantic line below centre of disc</del>				ins.
Distance between the top of statutory deck line on vessel's side and the intersec- tion of the continuation of upper side of <del>wood or</del> iron deck with the vessel's side		at <del>main, spar or</del> upper dk.	3 1/2	ins.
		at awning or pt.-awning dk.		ins.

NOTE.—It should be clearly shown whether the statutory deck line is set off from a wood or iron deck.

(Sgd) E.J. Milton Surveyor.

(To be filled up in London Office.)

Statement No. \_\_\_\_\_ Date of Committee's Minute \_\_\_\_\_

Moulded Depth for record . . . . . 33 ft. 6 ins.

Freeboards compared and found correct by \_\_\_\_\_ date \_\_\_\_\_

Is fee paid? \_\_\_\_\_ Form for Certificate \_\_\_\_\_

Instructions \_\_\_\_\_ date \_\_\_\_\_

Certificate written \_\_\_\_\_ Noted for posting \_\_\_\_\_

*Classification 100A1 "Shelter Deck" conditional on above freeboards*

