

Chief Ship Surveyor

Received from Chief Ship Surveyor

11 MAR 1924

NAME *WOOD Aux Twn Sc Sch. FLYING CLOUD* Rpt. *Intl* No. *5835*

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

DAMAGE.

Damage through

heavy weather.


The class of this vessel is subject to a Special Survey equal to a Half Time Survey being held at 8 years from date of build.

now repaired as follows:-

| | Plates | Frames | R. Frames | Floors | Beams | Str. Plates | Dk. Plates |
|--|--------------------------------|--------|-----------|--------|-------|-------------|------------|
| Renewed | | | | | | | |
| Removed and faired or repaired..... | | | | | | | |
| Faired or repaired in place..... | | | | | | | |
| Other items: | <i>Minor repairs effected.</i> | | | | | | |

It is submitted the vessel is worthy to remain as classed with *out*
record of Survey as recommended. *Subject as above.*

As now. Subject. &c.



© 2020
8.3.24

Lloyd's Register
Foundation

W1104-0068