

MARSEILLES

February 28th 1924

A.P. JONES

Owners representative survey the motor yacht "FLYING CLOUD" Plymouth for stress of weather damage stated to have been sustained when on voyage Nice to Marseilles February 12th 1924, to recommend the necessary permanent repairs. Further particulars see Log Books.

RECOMMENDED.

Light glasses on port side of
and deck house broken.

Glasses to be renewed.

Boat strained and planking
ed.

To be generally repaired &
planking partly renewed.

Boat davits bent & brackets
ed.

Davits to fair, brackets to
remove fair and refasten.

Boom & out-rigger boom broken

Both to be renewed.

Motor launch strained &
lanes damaged.

To be repaired.

Boat wedging & cover damaged.

To be repaired and canvas
renewed.

Room skylights damaged.

To be repaired.

continued

W1104-0069 1/2

© 2020

Lloyd's Register
Foundation

RECOMMENDED .

ok caulking in way of

is strained .

To be caulked .

caulking strained .

To be caulked .

MACHINERY.

auxiliary engine

Cylinder and crank case to be
renewed .

lar and crank case

carried away at flange

bed plate .

All the above recommendations were carried out under
and to my satisfaction .

account : Frs : 700

40,00

signed : A.P. JONES .

Frs : 740,00

Surveyor to
Lloyd's Register of Shipping
Marseilles .

W1104-0069 2/2



© 2020

Lloyd's Register
Foundation