

Steel Aux. Yacht "FLYING CLOUD".

A plan showing the arrangement of watertight bulkheads as fitted in the vessel has been received from the Genoa Surveyors.

In their letters of the 4th and 5th instant covering the same additional particulars are given to enable a suitable notation of BHs to be assigned.

Before however the case is dealt with, it is submitted the Surveyors should be asked to state whether the second deck is not watertight from frame 63 right aft including the portion of the deck from frames 32 to 35, and that portion of the deck at the middle line in the passageway from frames 20 to 32.

No 445/5/37
and 10th
1/1945
P.C. Livi

BCL
10.5.27.



© 2020

Lloyd's Register
Foundation

W1104-0079