

The SALVAGE ASSOCIATION have received the following telegram
from Lloyd's Agent at Panama, dated 22nd February, 1919.
re "ELIZABETH RUTH"

Sailed sixteenth returned today leaking $3\frac{1}{2}$ inches hour when
engines working, less when not working. Doubtless weakness
construction, cannot stand vibration. My personal opinion
vessel be unloaded for thorough inspection. Instruct.



© 2020

Lloyd's Register
Foundation

W1104-0285