

E.S. Humber

Panama.

Lloyd's Agent.

Panama,

REF. M/S "ELIZABETH RUTH"

SUBJECT: report on

The Secretary,  
London Salvage Association,  
19, Birchin Lane,  
LONDON.

Dear Sir,

Since writing to you on the 4th instant Surveyors have been watching the "ELIZABETH RUTH" very closely in order to decide as to whether she should be dry docked or not and have at last come to a decision as per enclosed copy of report No.479/18 whereupon I cabled you today:-

"ELIZABETH RUTH SURVEYORS DECIDED INSTALLATION  
ADDITIONAL CENTRIFUGAL PUMP SUFFICIENT PLACE  
SHIP SAFETY DRYDOCKING BALBOA UNNECESSARY  
ENGINE REPAIRS PROCEEDING."

From all I can gather it will be about three weeks before the repairs to engines will be completed.

I enclose copy of Captain's and Engineer's log book from August 30th to December 3rd 1918, and September 3rd to December 4th 1918, respectively, as supplied to me by the Master.

Yours faithfully,

(Signed) E.S. Humber.

Lloyd's Agent.



© 2020

Lloyd's Register  
Foundation

W1104-0289