

MON. 11 JUL. 1921

(Received at London Office)

No. 10982

L. 8.

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report *9th July 1921* When handed in at Local Office *9th July 1921* Port of *Southampton*

No. in Reg. Book *4924* Survey held at *Southampton* Date, First Survey *8th July* Last Survey *8th July 1921*

on the ~~Wood, Iron or Steel~~ *of hull of ~~Demolin~~ & ~~Tota~~* Master *J.C. Laidlaw*

TONNAGE: Built at *Wegesack* By whom *Bremen Vulkan* When *1917* Port belonging to *London*

GROSS *7856.74* Owners *H.M. Lines Ltd.* Owners' Address *Ellerman Lines Ltd.*

UNDER DECK *7266.15* Owners' Address *Ellerman Lines Ltd.* (if not already recorded in appendix to Register Book.)

NET *4924.83* Surveyed Afloat or in Dry Dock? *afloat* Name of Dock *Lon. docks* Destined Voyage

WB=CellDBorDBa feet; u&B feet; f feet; } Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

total capacity tons. FPT tons; APT tons; MT tons. } CHARACTER: * for Special Survey. Date of last Survey and of Periodical Surveys. Years Assigned for special survey. Machinery and Boiler Surveys (including date of N.B., if any).

Last Report, No. *Port* *Unclassed.*

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? *Was a damage report made by anyone else? If so, by whom?*

REPAIRS, OR EXAMINATION AS PER RULE, FOR *Classification survey (please see Lon. reg. 10974)*

Non done
Deep tank, after peak tank top, and Downston pump tested.
To complete the survey the stream anchor to be tested.
Freeboard to be assigned verified.

SUMMARY OF DAMAGE REPAIRS :-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	Stringers	Dblng. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Felt.) When put on, Month Year
Becks	Inner Bottom Plating	Engine Room Skylights	Boats
Caulking of Decks	State if Tanks have been examined inside	Coal Bunkers, Open gs, Lids, &c.	Masts, Yards, &c.
Waterways	State if Tanks now tested	Scuppers	Condition, how ascertained. <i>Abve.</i> (State if wedges removed)
Coamings	Bulkheads	Cargo Hatchways	Sails
Beams & Fastenings <i>Survey</i>	Ceiling <i>Confined</i>	Hatches of Wood Vessels	Equipment letter
Outside Plating	Cement or Asphalt (State which.)	Caulking	Anchors, No. of
Caulking of ditto	Rudder	Treenails	Cables (State if now ranged)
Rivets	Steering gear and its connections	Breasthooks & Stemson	" length (on board) size
Breasthooks & Crutches	Windlass	Transoms, Pointers, & Crutches ditto	" Rule length size
Transoms	Have Pumps now been examined and found efficient?	Timbers of Frame at openings ditto	Hawser & Warps
Frames	Have Sluice Valves now been examined and found efficient?	Ditto ditto at other places ditto	Standing & Running Rigging
Reverse Frames	Have Watertight Doors now been examined and found efficient?	Stringers, Clamps & Shelves ditto	
Floors		Salting (State if examined.)	
Keelsons			

General Observations, Opinion as to Class, Recommendation, &c.:-
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example: "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and pnd15, &c."

This vessel is eligible, in our opinion, to have the notation S.S. Sou. No. 1-7.21, with record of survey 7-21, when the vessel is classed, subject to the stream anchor being tested, at owners' convenience

Survey Fee (per Section 25) £
Special Damage or Repair Fee (if any) (per Sec. 26) £ *110*
Travelling Expenses (if chargeable) £
Second Surveyor's Fee (if any) £

Fees applied for per br. to Don 13/7/21
Received by me, *22.7.21 G. Dryden Toyne & A. Wilby's.*
Surveyor to Lloyd's Register of Shipping.

Committee's Minute
Character Assigned *See 7.6 report*

FRI. 22 JUL. 1921
TUE. 9 AUG. 1921
FRI. 16 JAN 1925
FRI. MAR. 24 1922
TUE. 27 FEB. 1923
TUES. 10 MAR 1925
FRI. 21 AUG 1925
FRI 9 MAY 1924
TUES. 31 MAR 1924

11105-0037

Is Certificate required? If so, to be sent to

