

## REPORT of SURVEY for REPAIRS, &amp;c.

Date of writing Report 19... When handed in at Local Office 19... Port of LONDON

No. in Survey held at  
Reg. Book.86488 on the ~~Wood, Iron or Steel~~ *Sc. St.* *TOYEN MARU.*

Date, First Survey

Last Survey

19

(No. of Visits)

TONNAGE

GROSS 3460.

UNDER DEK 2886.

NET 2173.

Built at

Stockton

Owners

Osaka Shosen K. K.

Managers

By whom

Craig, Taylor &amp; Co. Ltd

When

1905

12.

Owners' Address

(if not already recorded in Appendix to Register Book).

Port belonging to Osaka.

Surveyed Afloat or in Dry Dock?

Name of Dock

Destined Voyage

WB=CeUDBorDBa

feet; uE&amp;B

feet; f

feet

total capacity

tons. FPT

tons. APT

tons. MT

feet

tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 6073 Port Kob.

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Particulars of Classification (which must be inserted precisely as in Register Book &amp; Supplements).

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years since last survey.	Machinery and Boiler Surveys (including date of N.B., if any).
+10071 Spark 4.28		+LMC 4.28
S.S. Kob. No. 3-10.17		T.S. 4.28
S.S. Kob. No. 2-25.		

Society's Freeboard (if assigned) as  
painted on Ship and now verified } ft. ins.

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

## SUMMARY OF DAMAGE REPAIRS:—

	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

## PRESENT CONDITION OF THE

Decks	State if Tanks have been examined inside	Dblig. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Felt). When put on, Month Year
Caulking of Decks	State if Tanks now tested	Engine Room Skylights	Boats
Coamings	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Scuppers	Condition, how ascertained. (State if wedges removed)
Outside Plating	Cement or Asphalt (State which.)	Cargo Hatchways	Sails
Breasthooks	Rudder	Hatches	Equipment letter
Transoms	Steering gear and its connections	Planking of Wood Vessels	Anchors, No. of
Frames	Windlass	Caulking ditto	Cables (State if now ranged).
Reverse Frames	Have Pumps now been examined and found efficient?	Treenails ditto	" length size (on board)
Longitudinals	Have Sluice Valves now been examined and found efficient?	Breasthooks & Stemson ditto	" Rule length size
Transverses	Have Watertight Doors now been examined and found efficient?	Transoms, Pointers, & Grutches ditto	Hawser & Warps
Floors	Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings ditto	Standing and Running Rigging
Keelsons		Ditto ditto at other places ditto	
Stringers		Stringers, Clamps & Shelves ditto	
Inner Bottom Plating		Salting ditto (State, if examined.)	

## General Observations, Opinion as to Class, Recommendation, &amp;c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.24," or "to remain as classed and to have record of survey, 1.24, and the notations of ss No. 1-24 and ptND24, &c."

Survey Fee (per Section 29) £

Special Damage or Repair Fee (if any) (per Sec. 29) £

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

Fees applied for,

19

Received by me.

19

Committee's Minute

TUE. 23 APR 1929

Character Assigned

Write down in 28/4/29

N.B. (Spec.)

Surveyor to Lloyd's Register of Shipping.

General Committee  
Thursday 25th April 1929  
Lloyd's Register  
Classification Committee's  
decision confirmed