

2 FEB 1929

Sent to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME ~~Stl. No. 1~~ "SOCONY No. 1"

Report \_\_\_\_\_

Lon. \_\_\_\_\_

No. 93511

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)




Nature of Survey \_\_\_\_\_ When due \_\_\_\_\_

The S.S. No. 1 became due 10, 28.

The Nagasaki Surveyors now state they have been informed by the Owners that they do not wish to continue the classification.


It is submitted the vessel's class be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw class  
Insert ...

1.2.29

© 2021



Lloyd's Register  
Foundation

W006-0168