

s.s. "ORLA".

-----


This case is stated in the endorsements dated the 4th and 8th instant.

The following telegram has been received from the Owners today:-

Orla your letter 9 all boiler directions will be executed Buenos Aires but as sterntube in good condition hope you will allow extension until arrival Europe and meantime can order new from Builders stop Essential have your sanction that Ship has Lloyds Class in order to charter homewards, telegraph immediately".

IT IS SUBMITTED the Buenos Aires Surveyors be formed by cable that to entitle the vessel <sup>TO</sup> have her class <sub>h</sub> reinstated all safety valves require to be adjusted under steam, the vessel generally examined and the condition of the stern tube ascertained with a view to its renewal being deferred till the vessel's arrival on this side.

The Surveyors should cable the result of their survey to this Office immediately on completion.



15.4.29.

Lloyd's Register  
Foundation

W1109-0146

*Where  
Commenced  
decisions  
Secretary  
entirement*