

Rpt. 8.

(Received at London Office)

W1109-0172

DISCLOSED

No. 81

No. 3483

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 10 When handed in at Local Office 19 Port of LONDON

No. in Reg. Book. Survey held at Date, First Survey Last Survey 19

on the Wood, Iron or Steel "Orla" (No. of Visits)

TONNAGE: Built at Newcastle By whom J. S. B. Co. Ltd. When 1914 5

GROSS 4032 Owners D/S A/S Eidsvold Owners' Address

UNDER DEK 2536 Managers H. Waterbold Port belonging to Bergen

NET 2536

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

WB=CellDBorDBa feet; uE&B feet; f feet Particulars of Classification (which must be inserted

total capacity tons; FPT tons; APT tons; MT feet tons. precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 6073 Port Stav.

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.

+ 100 A1 + LMC 627

8.28 T.S. 626 ct

x. S.L. No 3-627

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed ...								
Removed and Paired or Repaired ...								
Paired or Repaired in place ...								

PRESENT CONDITION OF THE

Decks	State if Tanks have been examined inside	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Caulking of Decks	State if Tanks now tested	Engine Room Skylights	(State if on Feet)
Coamings	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month Year
Beams & Fastenings	Ceiling	Scuppers	Boats
Outside Plating	Cement or Asphalt (State which.)	Cargo Hatchways	Masts, Yards, &c.
Breasthooks	Rudder	Hatches	Condition, how ascertained
Transoms	Steering gear and its connections	Planking of Wood Vessels	(State if wedges removed)
Frames	Windlass	Caulking ditto	Sails
Reverse Frames	Have Pumps now been examined and found efficient?	Treenails ditto	Equipment letter
Longitudinals	Have Sluice Valves now been examined and found efficient?	Breasthooks & Stems ditto	Anchors, No. of
Transverses	Have Watertight Doors now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)
Floors	Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings ditto	" length size
Keelsons		Ditto ditto at other places ditto	" (on board) size
Stringers		Stringers, Clamps & Shelves ditto	" Rule length size
Inner Bottom Plating		Salting ditto	Hawser & Warps
		(State if examined.)	Standing and Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

Survey Fee (per Section 20) £
Special Damage or Repair Fee (if any) (per Sec. 20) £
Travelling Expenses (if chargeable) £
Second Surveyor's Fee (if any) £

Fees applied for,

19

Received by me,

19

FRI. 5 APR 1929

TUE. 16 APR 1929

Surveyor to Lloyd's Register of Shipping.

General Committee

Thursday 31st January 1929

Lloyd's Register

Foundation

decision confirmed as

Committee's Minute

Character Assigned

with a view to

TUE. 23 JAN 1929

Wrote Com. on 31/1/29

(The Surveyor)

Is Certificate required? If so, to be sent to

FBI. 6 APR 1923

Adhere to previous decision

Crown 79/11/29
 Dr Ben

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

When Anchors or Cables are supplied, the particulars are to be reported in the following form:—

ANCHORS.

Number of Certificates.	Anchors.*	WEIGHT IN STOCK. Cwts. qrs. lbs.	WEIGHT OF STOCK. Cwts. qrs. lbs.	TEST, PER CERTIFICATE. Tons. Cwts. qrs. lbs.	WEIGHT REQUIRED BY RULE. Cwts. qrs. lbs.	Description of Anchor.	Makers.	Where and when tested and Superintended.
	1st Bower							
	2nd "							
	3rd "							
	Collector's Weight.							
	Stream							
	Keel.....							

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES.

[illegible]

If Stockless, state Mechanical Tests

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

Lloyd's Register
Foundation