

20. Soc. Ital. Ernesto Breda.

Gen. 9424,

This case receives further consideration
At the Genoa Surveys he requested to state
the tensile strengths of the shell plates, screw
girders are correctly reported as 44/55
44/55 kilograms respectively, the tensiles
the approved plan being 49/53, 41/47 &
respectively. They should also state the number
in the doubling plate of the shell near hole.
approved plan should be forwarded to the
for reference & returned with their reply.

J.P.H.
21/6/26

Lloyd's Register
Foundation

W1109-0217