

27 DEC 1929

s. s. "JADRAN".

A limit to repair the boiler expired at the end of June last.

The Susak Surveyor has now forwarded a letter from the Owners in which they state that they have decided to withdraw the vessel from class.

IT IS SUBMITTED the vessel's class be withdrawn from the Register Book and three dots inserted in lieu indicating withdrawal of class at Owners' request.

Withdraw class.

Insert ...

[Signature]
24.12.29.

© 2020

Lloyd's Register
Foundation

WHL-0122

Yours faithfully,