

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of London

DISCLOSED
BOX No. 8
(TOP)

No. in Reg. Book 24889 Survey held at on the Wood, Iron or Steel Sc "MARISKA"
Date, First Survey Last Survey 19
(No. of Visits)

TONNAGE - Built at Nakskov By whom A/S Nakskov Skibsvaerft Wh n 1921 - 11
GROSS 619 Owners Soc. Anon. di Nav. Giovanni Riboli Owners' Address
UNDER DEK 520 Managers Port belonging to Fiume
NET 355

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage
WB=CelldBorDBa feet; uE&B feet; f feet } Particulars of Classification (which must be inserted
total capacity tons. FPT tons; APT tons; MT feet tons. } precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 3076 Port Fiume

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

CHARACTER for Special Survey, Date of last Survey and of Periodical Surveys.	Years Assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
+100A1		+LMC
82Y		3.25
S.S. Lpr No 1-25		+LMC(M) 4.27 TS 8.37 CL
		Oil Eng.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as painted on Ship and now verified ft. tons.

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

M-4/100

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE			
Decks	State if Tanks have been examined inside	Dblng. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessel (state if on Felt). When put on, Month Year
Caulking of Decks	State if Tanks now tested	Engine Room Skylights	Boats
Coamings	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Scuppers	Condition, how ascertained (state if wedges removed)
Outside Plating	Cement or Asphalt (state which.)	Cargo Hatchways	Sails
Breasthooks	Rudder	Hatches	Equipment letter
Transoms	Steering gear and its connections	Planking of Wood Vessels	Anchors, No. of
Frames	Windlass	Caulking ditto	Cables (state if now ranged)
Reverse Frames	Have Pumps now been examined and found efficient?	Treenails ditto	length size (on board)
Longitudinals	Have Sluice Valves now been examined and found efficient?	Breasthooks & Stemson ditto	Rule length size
Transverses	Have Watertight Doors now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Hawser & Warps
Floors	Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings ditto	Standing and Running Rigging
Keelsons		Ditto ditto at other places ditto	
Stringers		Stringers, Clamps & Shelves ditto	
Inner Bottom Plating		Salting ditto (state if examined.)	

General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptnD24, &c."

Survey Fee (per Section 20)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 20)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me.
Second Surveyor's Fee (if any)	£	:	:	19

Committee's Minute TUE. 10 DEC 1929

Character Assigned insert (" ")
Mule on Lo. 12/12/29

Surveyor to Lloyd's Register of Shipping
Special General Committee
Thursday, 12th Dec 1929
Lloyd's Register
Classification Committee
Foundation
decision confirmed
W111 - 0198

The Surveyors are requested not to write on or below the space for Committee's Minute.

Is Certificate required? If so, to be sent to