

ft. Are the discharge pipes above or below the deck quarter line
to Spacary.

Are they each fitted with a discharge valve always accessible on the platform valves
Lon. 91742

It is submitted that
this vessel is eligible for
THE RECORD. Date 8-27.

oil engines 2 sets. 34 NHP.
2 cy. 13-13 3/8.
1 set. Bolinders belt.
Skew.

B.R. 29/8/27.

W1114-0035

thickness working pressure by Rules No. of starting air receivers
Total cubic capacity Material Seamless, lap welded or riveted longitudinal joint