

Steel Screw Steamer "EILENAU"; No. 40205 in the Supplement to  
the Register Book;  
1521 tons gross; Built in 1910 - 8 mo.; Port - Bremerhaven;

9


Owners: Bugsier Reederei und Bergungs Aktiengesellschaft  
(W. Schuchmann, Manager)

Classed: \* 100A1 \* LMC - MS 1,27  
Shelter deck with freeboard MBS 6,28  
12,28 NDB - 28  
s.s.No.3-1,23 TS 11,29.  
s.s.No.1-27.

The Main Boiler Survey of this vessel became due in June last, and to complete the same the safety valves require to be adjusted under steam.

In a letter, dated 7th instant addressed to the Society's Surveyor at Bremen, the Managing Owner states that the steamer has been transferred to the classification of the Germanischer Lloyd.

The Classing Committee had the case before them on Tuesday, 18th instant, and in the circumstances decided to give instructions for the vessel's character to be withdrawn from the Society's Register Book and three dots (...) inserted in lieu thereof, indicating withdrawal of class at Owners' request.



20th February, 1930.



© 2020

Lloyd's Register

W1115 0132  
Foundation