

W1119-0149

Gen. 2702.

Submitted the Genoa Surveyor
 be requested to state the W.P. to which
 the main boiler safety valves are adjusted, if
 casing gear is fitted to same & the smallest
 distance between boilers & uptakes & ladders
 or woodwork.

Dr Tolson
 11/11/02



© 2020

Lloyd's Register
 Foundation

No. of Feed pumps _____ Diameter of ditto _____ Stroke _____ Can one be overhauled while the other is at work _____

Can one be overhauled while the other is at work _____

Lloyd's Register of Shipping, 56, John Street, Sunderland.

911
360
152
791
2194

911
360
152
791
2194

198
03
594
124

+ 63
479
1109

189



© 2020

Lloyd's Register Foundation