

COPY.

28th June, 1932.

CARDIFF.

19703, 14, 15, 16, 17. As recommended.

19057. "CHISWICK MANOR". In connexion with the 1st Special Survey No.3 on this vessel, which became due in April 1931, the Owners have called attention to the fact that in January/February, 1931, the steamer underwent extensive repairs under your supervision, and, ^{state} in ordinary circumstances, "a good deal of the work then done would have counted as part of the survey, but as the survey date had not arrived, we took no measures in that direction".

They have now requested that this survey may be accepted as part of the Special Survey, and as it is observed from your report that the vessel was examined in dry dock, the Nos.1 & 2 double bottom tanks tested in way of the repairs and found satisfactory, and the weather decks, hatchways, hatches, ventilators and equipment were generally examined and found,



© 2020

Lloyd's Register
Foundation

01121-011312

COPY.

CARDIFF.

28-6-32.

"CHISWICK MANOR" - Contd.

or placed in order, I have to request you will be good enough to state whether these parts might be credited as part of the Special Survey No.3.

I may add that the Owners point out the steamer has been laid up during the whole of the year of grace, so that "there has been absolutely no wear and tear."



© 2020

Lloyd's Register
Foundation

W1121-0173 2/2