

4E

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor 110 APR 1933

EL'S NAME Steel Sc. "CHISWICK MANOR" Rpt. Cff No. 50100

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey ~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

The Special Survey No.3 and Boiler Survey became due 4,31.

The survey of the engines was partly held in 2,31 and since then the vessel has been laid up.

The Cardiff Surveyors now report the survey of the engines has been advanced, and to complete same minor repairs are required to the port boiler and the steering engine.

The vessel is still laid up indefinitely.

It is submitted action be deferred.

SA
7/4/33



© 2020

Lloyd's Register
Foundation

W1121-0198

+LMCM.S. 2.31, (see letter mentioned above to) and O.S. 8.32, when