

1

*Chiswick Manor*

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel S.S. "LOMBARDIER". Report Gls. No 38676

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement. - Extract from Sub-Committee's Report, 24/5/22.)

Nature of Survey

When due

This vessel was originally named "WAR TAY".

The downton pump has been dispensed with as approved in Standard Vessels, and it is concluded the present Owners are agreeable to fit same at the end of the War, if requested to do so.

100 A.1. (Steel).

1 Dk. (Steel).

Cell DB 198' 297t. FPT 84t. APT 60t.

FK. 4 BH. Cen. Lloyd's A. & C.P. B52' F23'.



© 2020

25. 4. 19

Lloyd's Register  
Foundation

BEAMS, Third and Fourth Deck, Single Angle, Bulb Angle, Plate, Tee Bulb, or Channel

Poop Deck Stringer Plate, breadth & thickness

Angle on ditto

Tie Plates