

Last Report, No. 63283.

Port GLS.

W1126-0090

Rpt. 14.

Port of HULL.

3rd May,

19 41.

REPORT ON MASTS, SPARS, AND RIGGING.

Dear Sirs,

Having, in accordance with your instructions, examined the Masts, Spars, Iron Work of same, and Rigging, of the

(Name of Vessel) "CARSBRECK"

on the (Date of examination) 2nd May,

19 41,

I have to report that I found FOREMAST - (damaged by explosion).

Extensive repairs to mast; Shrouds, stays and screws renewed.

Forestay and foretopmast stay screws and shackles require overhaul.

MAINMAST - in good condition. Shrouds, stays and screws in good order.

MERRICK POSTS → Port and starboard stays require renewal. Cross stay rigging screw requires renewal.

FUNNEL STAYS - Port and starboard outer stays require renewal. Other stay in good order.

Fee £ - : 10 : -

To the Surveyors,


Lloyd's Register of Shipping,

HULL.

2m,334

Chas S Acklam

above repairs effected as recommended.



2020

Lloyd's Register Foundation

* 100 A1

ard (if
ip and
hom?

Adlan

632

Exa

D.E

Con

lock

tank

7, A

tem: -

bu list

+

Copper, or
(State

When fitted

Boats

Masts, Yards

Condition, L

(State

Equipment

Anchors, N

Cables (Sta

length

Rule

Chain Lock

Hawsers &

Standing an

Sails

in the Re

remain as cl

surve

and notation of S.S. 1st

(By ...)