


9 10

[illegible]

RETAIR

Plan of crankshaft
Deutsche Werft's Nos. 82/83
Hamburg letter 4. 2. 1925.

Chinese Prince

Hamburg Report Nr. 16924



© 2020

Lloyd's Register
Foundation

W1126-0178