

total capacity/ tons. FPT tons; API tons; M1 feet tons.
Only alterations in the existing records of tanks should be inserted.
N.B.—All alterations in the existing records should be underlined.

10.38.

13 AUG 1942

to Chief Surveyors

Received from Chief Surveyors

SEL'S NAME

EMPIRE AVOCET

Report Liv.

No. 118116

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ure of Survey

DOCKING

~~When due~~

Noted.

31.7.42

was

R.B.

Amend

7BH (4 to sh.dk)
(3 to 2nd ")

TO

7BH (5 to sh.dk)
(2 to 2nd dk)

2 tween dk BHs dispensed with

1 tween dk BH dispensed with.

Insert

416.5 (O.L.).



© 2020

Lloyd's Register
Foundation

W1130-0070

in way of sidelights	Windlass	Hatches
----------------------	----------	---------

Condition, how
(State if a
Equipment le