

No. of
Do. of Houses on Dk. 161-36
Do. of excess of Hatchways 50-64

Length on deck from fore part of stem to after part of stern post 380-5

By whom built Goddard
at Seattle
Wash. Sta

CABLEGRAMS: NYMDIBLE, NEW YORK

TELEPHONES { 1363 } RECTOR
{ 1364 }

LLOYD'S REGISTER,
LONDON.

LLOYD'S REGISTER OF SHIPPING,
17 BATTERY PLACE


REC'D DEC 21 1918
ANSD

NEW YORK December 18, 1918.

Dear Mr. Scott:

With reference to your letter of the 14th ultimo and to Seattle report No.675 on the steamer "ANACORTES", I enclose herewith a letter dated the 10th instant received from the Surveyors from which it will be seen that the butts of the bilge and side plating is treble riveted, instead of half length as recorded in the report; also that the transverses are connected to shell with double angles in forehold as per approved plan.

Yours faithfully,



A. Scott, Esq.,
LONDON.



© 2020

Lloyd's Register
Foundation

W1131-0025

W1131-0026

W1131-0028

Vertical text on the right edge of the page, including fragments like 'in D', 'No.', 'No.', 'Dk.', 'ness', 'ing.', 'ness', 'te.', 'ess', 'always'.

