

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME STEEL S.S. "LORAIN" Report N.Y.K. No. 16769**For the CHIEF SHIP SURVEYOR**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 34/592.)

Nature of Survey

When due

The Downton pump has been dispensed with for the present.

❖ 100 A.1. (steel) "Shelter Deck with Freeboard"

1 Dk. (steel) and Shelter Dk. (steel), and Webframes.

"Longitudinal Framing"

Cell DB 331' 1512t. PPT 187t. APT 175t.

FK. 7BH. to Shelter Dk. Cem. A. P.C.P. P45', B 110', F38' on Shelter Dk.

Particulars for Record
in Register Book.

Freeboard

Corresponding Draught

27 ft. / ins.

© 2020

Lloyd's Register
Foundation

asb.

7.7.19