

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

19th October, 1935.

Dear Sirs,

With reference to your First Entry Report No.8673 on the Machinery of the motor vessel "FERNANDO POO", it is concluded the emergency dynamo was built under survey in accordance with Section 2, clause 6, of the Rules for Heavy Oil Engines, but I shall be glad if you will state if this is so. If the engine was built in your district you should forward the usual report 4c.

At the same time I have to request that you will be good enough to state what the boiler can be used for.

With regard to the electrical motors, I have to point out that you have omitted to forward with the First Entry reports the necessary certificates of the electrical machines. It is a requirement of Section 2, clause 1, and Section 11, Clause 2, that machines above 100 KW or HP are to be surveyed during manufacturing and testing, and a special report Rpt.7 b should be completed by you witnessing the tests. For smaller machines for essential services the Makers' test certificate should be obtained and attached to the reports.

I shall therefore be glad if you will kindly obtain and forward these certificates to this Office as soon as possible.

I am, Dear Sirs,
Yours faithfully,

The Surveyors,
BILBAO.

per Secretary.