

IT IS SUBMITTED that the Philadelphia Surveyors' attention
be called to the fact that in their report No.4231 on the
S.S. "AGWIHAVRE" the number of the donkey boiler test
certificate is given as ⁵¹²~~521~~ and that in their report No.4740
on the M.V. "CHALLENGER" the same certificate number is given
for the donkey boilers and they should be asked to explain.

EMS
1.5.24

Dr Phil 2/5/24



© 2020

Lloyd's Register
Foundation

W1135-0013

BEAMS, Forecastle Deck, Angle, Bulb Angle,
Plate, Tee Bulb or Channel
Angles on upper edge

8	3½	50	8	3½	50
---	----	----	---	----	----

Forecastle Deck Stringer Plate, Angle on ditto
Tie Plates