

Yewelland

The N.H.P. for this vessel should be 469.
& should be allied according in the RB


Ym

27.9.36

NOTES FOR POSTING

AM

Yoke returned to ground floor. after removal.



Lloyd's Register
Foundation

W1133-0200

the exhaust tubing is 58" and the B.H.P. of