

by Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor \_\_\_\_\_

SHIP NAME St. S. K. ST DONATS.

Rpt. Itul No. 35476

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/93.)

of Survey \_\_\_\_\_

It is submitted before this case receives the consideration of the Committee the Surveyor should be requested to state whether the sheerstrake butts are lapped, or strapped <sup>as</sup> shown on the approved midship section, and why the decks and bulkheads were not tested.

A plan should be forwarded showing the vessel as built

Lr: - 18/9/24.

*[Signature]*

*[Signature]*

*[Signature]*  
18-9-24



© 2021

Lloyd's Register  
Foundation

W1136-0104

W1136-0105