

11,39.

31 MAY 1940

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME "ST. GLEN" Rpt. Hul No. 50683

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Action has been deferred for examination in dry dock after grounding.

The Hull Surveyors report the vessel placed in dry dock, the bottom coated, and on account of damage through grounding a few shell rivets made good.

It is submitted the vessel appears worthy to remain as classed with record of survey 5.40.

100A1
Shelter dk with freeboard
5.40 Hul

S.R.L / Delete dry docking (grounding)



© 2020

Lloyd's Register
Foundation

W1138-0153