



Lloyd's Register of Shipping.

LLOYD'S REGISTER
Received
13 JAN 1938
And
LONDON

95, Bothwell Street, Glasgow, C.2.

12th January, 1938.

Dear Sir,

Reference
S.

In reply to your letter of the
11th instant respecting the Motor Tanker "BRITISH SECURITY",
I beg to acquaint you that the Surveyor states that the
after end of the screwshaft liner is made watertight in the
propeller boss.

I am, Dear Sir,

Yours faithfully,

J. L. Warlow

Secretary to the
Glasgow Committee.

The Secretary,
LONDON.



© 2020

Lloyd's Register
Foundation

W1140-0180

W1140-0180

Referred to Mr. Hill

RJH

13 JAN 1938

Ans 13/1/38

RECEIVED
13 JAN 1938

RECEIVED

13 JAN 1938

RECEIVED

RECEIVED
13 JAN 1938

RECEIVED



© 2020

Lloyd's Register
Foundation