

3m,11,39.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor 29 MAY 1940

VESSEL'S NAME

"SITALA"

Rpt.

Hav

No. 8353

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/02.*)

The Havre Surveyors report this vessel afloat and on account of damage through collision the shell plating on the starboard side aft in way of ammunition room, together with framing in way, was found indented.

The damage does not impair the seaworthiness of the vessel, and the Surveyors recommend the poop plating and framing (s.s.) in way of ammunition room be repaired at Owners' convenience.

It is submitted the vessel appears worthy to remain as classed without record of survey, subject as recommended.

As Now, Subject, etc.



© 2020

Lloyd's Register
Foundation

18 5 40
W1142-0126