

10 JUN 1942

nt to Chief Surveyors

Received from Chief Surveyors

ESSEL'S NAME

EAST INDIAN

Report

N.Yk.

No. 42361

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/42.)

A No. 1

**SURVEY PARTLY HELD**

ADVANCED & DOCKING.

then due

12.41

(vessel 23 yrs old.)

When proposed to be completed

not stated.

portion of Survey held, &c.

Examination of anchor, cables, chain locker, (10.41) and peak tanks also the testing of No.1 D.B. tank (4.42.)

Subject to defective rivets in No.1 D.B. margin lugs being dealt with at the first opportunity.

SHELL PLATING TO BE DRILLED AT THIS SURVEY.

S.S. PART HELD.

(Docking date)  
( 4.42 )



© 2020

Lloyd's Register  
Foundation

W1144

- 0092