

COPY.

Lloyd's Register of Shipping.



Port.....

NEW YORK

MAY 8th, 1942

This is to Certify that I have

Surveyed the.....

M.V. "EAST INDIAN" 8159 tons gross register of

Dearborn afloat and in dry dock for repairs and Part S.S. 3rd No.1

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, and that I have **Recommended** that she be.....

continued as classed

with fresh record of survey 4-42 and notation of S.S. 3rd No.1

with date when the survey has been completed, subject to renewal

of defective rivets in No.1 double bottom floor clips at Owners convenience.

being fit to carry.....

dry and perishable cargoes.

Now done for Part S.S. 3rd No.1

Fore peak and after peak tanks examined internally and found in good condition. No.1 double bottom tank tested and proven tight.

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."