

RETAIN

F.E.
(FBD.)

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

"LAFTAN"

Rpt.

Mdb.

No.

16175

Nwc.

9570

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long. No. 14179 Equiv. "D". Depth "d" 22.62
 2nd Long. No. 37626 " " Proportions = $\frac{L}{D}$ 10.87
 Framing Bulb angle frames as approved Sheerstrake As approved

The Newcastle Surveyors report this vessel placed in dry dock, the bottom cleaned and coated, the steam windlass, steam steering gear, and auxiliary steering gear tested and found satisfactory, and the Special Survey completed.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ~~100A1~~ "With Freeboard"

The Summer Freeboard as shown on the attached extract from the Freeboard Verification Form, now marked on the vessel's sides, to be inserted in the classification certificate and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying extract, to be inserted in the certificate of classification.

1 Dk. and Shelter Dk. Platform deck in Part No.2 hold


Cell.DB. 296' 1072t, MT 25' 931t, Tanks in way of tunnel 363t, FPT 183t, APT 139t.

FK, 7BH(Coll.BH to Shelter Dk., 6BH to 2nd Dk.) pt.asp., Lloyd's A & CP.

F 44'

O.L.438'-4".

This vessel is a sister ship to the "CONAKRIAN"



Lloyd's Register
Foundation

W1145-0005