

Lloyd's Register of Shipping,

LLOYD'S REGISTER.

EAGLE STREET,

LONDON.

BOX 465 G.P.O.

Brisbane,

2nd December 1921

10 JAN 1922

RECD

ANSD

Dear Sir,


I have much pleasure in enclosing herewith Certificates Nos. 1313, 1313A, 1313B and 1313C for the new steamer "ECHUCA" (Yard No.39) being respectively a First Entry, Report 4 Machinery and Boiler, Electric Light Installation and Freeboard with req.9 for Freeboard; Certificate of Boiler and Glasgow report No.40379 which was forwarded by the Society's Surveyor at Melbourne, also copy of Fees charged.

The Certificates are dated the day the vessel was handed over, but details had to be worked out and I only put in the account on the 23rd Novr. hence they are not paid. The fees were made up under instructions from Mr. Heron who has done everything to assist me.

I have applied for and been promised the following plans: Profile, Midship Section; Pumping Plan; and Tracing of Boilers, all of which will be forwarded as soon as received.

An error occurred in placing the wrong lengths of chain cable on board and will be rectified as soon as the second vessel No.40 is completed meantime this vessel "Echuca" No.39 is not in commission, nor is it likely that she will be for sometime.

During the steam trials the "Echuca" touched the fender pile with her starboard side and set in the plate at the



Deck. Material and thickness

Forecastle Deck Stringer Plate, b'dth & th'kns

2/Decr.1921

handing of G.H. this will be faired before she goes into commission, this and the error re cables is noted on the provisional Certificate issued, copy of which is enclosed, also provisional boiler and machinery certificate.

I sincerely trust that everything will be found correct and in order.

I am, Dear Sir,

Yours faithfully,

A. S. Scott
Surveyor

A. Scott, Esq.,

Secretary,

LONDON. E.C

Encls/



© 2021

Lloyd's Register
Foundation

Referred to the Chief Civil Surveyor,
and the Chief Engineer Surveyor.

CP-2

10 JAN 1902

Referred to Mr. Aschough.
Referred to Mr. Meyna.

BH
Cms.

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED



© 2021

Lloyd's Register
Foundation

TAYLOR,
SURVEYOR,
FIRST NAVAL ARCHITECT
OFFICE NO. 502
RESIDENCE NO. 1
TELEGRAPHIC ADDRESS
"SHREVEYOR"
DOES:
A.N.C. FIFTH EDITION