

6- JUN 1940

by Chief Ship Surveyor

Received from Chief Ship Surveyor

'S NAME "ROBERT" Rpt. Lon. No. 108730

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)


The Committee recently agreed that provided Danish vessels classed with the Germanischer Lloyd or Norske Veritas and taken over by the Ministry of Shipping were found or placed in satisfactory condition, for a period of six months, after general examination as set forth in Circular 1764, a record of Examined L.R. (With date) could be inserted in the Register Book.

The London Surveyors now report this vessel generally examined in dry-dock, bottom coated, a number of rivets renewed and/or overhauled and minor repairs carried out; some hatch covers have also been renewed.

In the Surveyors' opinion the vessel is eligible to have a record of 'Examined L.R. 5.40'.

It is submitted this recommendation be concurred in and a notation as recommended be inserted in the Register Book.

Insert in S.R.L.:- Exd. L.R. 5.40, for 6 mos.



© 2019
4.6.40
Lloyd's Register
Foundation

W115-0015