

Journal

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME Steel Screw "NARRAGANSETT" Rpt. Ham. No. 21883

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

1st Long. No. 17945 Depth "d" --

2nd Long. No. 51773.75 Proportions = $\frac{L}{D}$ 13.1

Framing Longitudinal framing Sheerstrake As approved

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *100A1 'Carrying petroleum in bulk'

1 Dk. 2nd Dk. clear of cargo tanks, 'Longitudinal Framing' Cell. DBuE 86' 184t, DTf 16' 540t, FPT 370t, APT: 244t.

FK, 16 BH, pt Cem. pt. Asp. Lloyd's A & CP.

P 107', B 39', F 35'

Machy. aft.

Rudder electrically welded

[Handwritten signature]
19/15.5.36 *[Handwritten initials]*



© 2021

Lloyd's Register Foundation

W1150-0054

220

Faint, mostly illegible text, possibly bleed-through from the reverse side of the page.



© 2021

Lloyd's Register Foundation