

SWAN, HUNTER, & WIGHAM RICHARDSON, LIMITED.

Ship, Engine, Boiler & Floating Dock Builders & Repairers,

WALLSEND-ON-TYNE.


London office, 21, Russell Square, W.C.1.



References Ours 6I.LC.
Yours

17th February, 1938.
Thursday.

The Secretary,
Lloyd's Register of Shipping,
71 Fenchurch Street,
LONDON E.C.3.



Dear Sir,

NOS. 1561 & 1563 SHIPS - AFTER END FRAMING.

We thank you for your letter of the 16th instant regarding the strong beam at the forward boiler room bulkhead, between frames 19 and 20 at the second deck level.

We note you think it necessary that this beam should be retained in this position and we are arranging accordingly.

Yours faithfully,

FOR
SWAN, HUNTER WIGHAM RICHARDSON, LTD.

I. Bocher

NAVAL ARCHT. NOT.



© 2021

Lloyd's Register
Foundation
W1150-0227

Telephone: WALLSEND 63121.

Telegraphic address: SWANHUNTER, WALLSEND.

All offers are subject to our usual strike, accident and guarantee clauses and to the other conditions in our printed form of contract.

Referred to the Chief Ship Surveyor.

18 FEB 1938

St Mont gomery

HB

Jim

John

YOUNG LLOYD

...the second deck level.
...the second deck level.
...the second deck level.

...the second deck level.
...the second deck level.
...the second deck level.

...the second deck level.
...the second deck level.
...the second deck level.

...the second deck level.

RECEIVED
FEB 18 1938

...the second deck level.
...the second deck level.
...the second deck level.

...the second deck level.
...the second deck level.
...the second deck level.

...the second deck level.
...the second deck level.
...the second deck level.



...the second deck level.

...the second deck level.

...the second deck level.



© 2021

Lloyd's Register
Foundation