

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

ESSEL'S NAME Single Deck "TOGSTON"Rpt. mdbNo. 11957

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

1st Entry.

This vessel has proceeded to Newcastle for the installation of the machinery—

It is submitted the Newcastle Surveyors be informed, that to complete the survey the following remains to be done:— Tunnel to be completed and hose tested. Fidley Covers, Screen bulkheads, and skylights on casing tops to be fitted, windlasses, winches, Steam & Hand steering apparatus to be tested, Cargo Hatch escape hatches to be fitted. Chain locker side & End plating to be stiffened at top edge. Hatch webs, covers & tarpaulins to be examined, and report on form 8 when the survey is completed.

Zr. Nwc. 2/6/24
p.c. Mdb.



© 2021

Lloyd's Register
Foundation