

For the information of Surveyors and the Committee only.

Received at

Office

19

Lloyd's Register of Shipping.

der: 368609.

(Report on Vessel No. 16726 Port Hamburg)

SHIP FORGINGS OR CASTINGS.

I have to report that the undermentioned ~~Forgings~~ Steel ~~Forgings~~ Castings, manufactured by Messrs. Fried. Krupp A.G. of Essen for the Vessel No. 480/81, being built by Messrs. Germania Werft of Kiel-Gaarden have been inspected by me as set forth below and found to be, so far as can be seen, 1 propeller bracket guide sound and free from surface defects.

Forgings or Castings.

Lloyd's

Düsseldorf 28th February 1925.

No. 179.

27.2.25.

1 propeller bracket

~~RUDDER FRAME.~~
guide

RUDDER FRAME.

STEM.

Annealed Siam Mart. Cast Steel
cast

on Inspection ... rough turned

on Inspected { 27.2.25.

ASTINGS.

.798

3"

Standard Test
Pieces.

Test—

square inch

30,4

29,5

on per cent. ...

33,3

36,0

ding Test—

before fracture

120 degr. good

Test—

from ground ...

10 feet

ing Test—

according to Rules

and satisfactory ...


satisfactory.

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

(if any chargeable) £

To be paid at Düsseldorf.

Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.



© 2020

Lloyd's Register
Foundation

WISI - 0014 21/4/25