

7 - NOV 1928

Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

EL'S NAME Steel "SYDNEY" Report Lon. No. 93220a**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/02.)

ure of Survey \_\_\_\_\_ When due \_\_\_\_\_

The Special Survey No.1 became due 9,28.

The new Owners now state they have decided not to carry out the survey.

It is submitted the class of the vessel be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw Class.

Insert ...



© 2020

Lloyd's Register  
Foundation

7.11.28.

W1152-0015