

Ass Report 15633 A. & B.

Gebr Stork. Eng Nos 4168 and 4198.

It is submitted that before this case receives consideration the Surveyor should be requested to confirm their statement that the thickness of Main and Aux crank shaft webs are 272 mmS and 48.5 mmS respectively, whereas the approved plans show 315 mmS and 50.5 mmS

Li. 2/5/39.

7.S.
1.5.39

L.Y.

L. 1/5



© 2020

Lloyd's Register
Foundation