

129 NOV 1938 1

Inspected by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

"SIAM"

Rpt.

Cpn.

No.

10730

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

## DAMAGE.

Nature of Survey

Damage through striking quay, and sailing among wood logs.

now repaired as follows:-

|  | Shell<br>Plates | Main<br>Frames | R.<br>Frames | Floors &<br>Bracket<br>Floors | Inner<br>Bottom<br>Plates | Deck<br>Plates | Beams |
|--|-----------------|----------------|--------------|-------------------------------|---------------------------|----------------|-------|
| Renewed .....                          |                 |                |              |                               |                           |                |       |
| Removed and faired<br>or repaired..... | 3               |                |              |                               |                           |                |       |
| Faired or repaired<br>in place.....    | 2               | 3              |              |                               |                           |                |       |

Other items:-

The vessel placed on a pontoon, bottom cleaned and coated and minor repairs carried out.

It is submitted the vessel is worthy to remain as classed with  
record of Survey 11,38

100A1

Shelb'dh with Leadboard

11,38 Cpn.