

Nº 663 (etched) x100

Micrographs


From wrapper plate

Section including portion of  
rivet hole.

S.S. "Chulmleigh"

Port Boiler - Defective wrapper plate  
+ rivets

Secretanys letter 26-8-'42



Nº 664

x100

Nº 63-934



© 2020  
Lloyd's Register  
Foundation

(LR)  
28-9-42